

Models 3200 & 4200

Residential Whole-House



Improve Health

Protect Assets

Enhance Comfort

Reduce Furnace Energy Costs

A Whole-House Humidifier:

- Treats Your Whole House 24 / 7 / 365
- Requires Minimal Maintenance
- Is Out of Sight
- Runs Quietly





Winter months mean drier indoor air.

When the air in your home is too dry, you know how unpleasant it can be.

Health concerns

The right humidity levels keep your sinuses and throat healthy, reducing the incidents of cold, flu, respiratory infections, allergies, asthma, and bloody noses. Studies show that humidity that's too low contributes to the flu virus surviving longer, while simultaneously increasing its ability to spread from one person to another.

Dry, itchy, cracked skin

Dry air causes your skin to dry as well, and left untreated can cause anything from minor discomfort to cracked, bleeding skin.

Temperature discomfort

Dry air causes air to feel cooler than it really is, leading you to turn up the thermostat. The result is even drier air and a higher heating bill. Adding humidity saves money.

Damage to your home and assets

Dry air pulls moisture from your home's wood framing, trim, flooring, and furniture. Expensive artwork and musical instruments can become damaged. Dry air causes gaps between ceilings and walls, letting in cold winter air and increasing the cost of your heating bill.

- Air that's too dry affects your health, your comfort, your home, *and* your pocketbook.

Static shock

When the air is too dry, static electricity begins to build up. This can cause blankets and clothes to stick together and, more importantly, cause painful electric shocks when you touch a doorknob or another metal surface. Static shocks can damage expensive electronics.

GeneralAire® Has Your Solution



Maintain the right humidity throughout your entire home with the **GeneralAire® Evaporative Humidifier Models 3200 & 4200** to protect your home and its contents, while also offering you and your family greater health and comfort.

The Benefits

- Minimal maintenance.
- Treats the entire home.
- Offers maximum humidity output.





GeneralAire® Evaporative Humidifier Models 3200 & 4200 Residential Whole-House

GeneralAire® Evaporative Humidifier Models 3200 & 4200 Feature:



- Innovative, Space-Saving Design
- Enhanced Output Through:
 - New Distributor Trough Design Distributes Water Evenly Over Pad
 - Stainless Steel Distribution Tube Allows for Hot Water Supply
 - Low-Profile Cover Forces Air Through Vapor Pad at it's Warmest Point
- Easy & Quick Vapor Pad® Replacement Through:
 - Snap-in-Place, Easy-Lift-Off Cover
 - Sturdy "Pull Apart" Two-Piece Vapor Pad® Frame
- UV Stable Cover
- MHX3C Manual Humidistat Included With M Models Only
- GFX4 Automatic Digital Humidistat Included With A Models Only
 - Controls the Furnace Blower Motor
- Model 3200 Is Suitable for Homes Up to 3200 Square Feet
- Model 4200 Is Suitable for Homes Up to 4200 Square Feet

The Comprehensive Approach to Indoor Air Quality

Creating a healthy indoor air environment requires a comprehensive approach; one that eliminates harmful pollutants and sources of discomfort in your home. Humidity control, air purification, and particulate removal are equally important components of that plan.

Installing MAC Air Cleaner with a MERV 11 filter will remove airborne dust, dust mites, pollen, pet dander, and other airborne pollutants as small as 1.0 microns (a human hair is 75 microns). Reduce allergy and asthma triggers with a MAC air cleaner.

Contact your local contractor to learn more about how to create a healthier and more comfortable home for you and your family. And visit us at www.generalfilters.com for more on indoor air quality.







Evaporative Models	3200	4200
Order # (MHX3C Manual Humidistat) (M Models)	5800	5950
Order # (GFX4 Digital Automatic Humidistat) (A Models)	5801	5951
Туре	Evaporative Bypass Humidifier	
Home Size (Square Feet)	Up To 3,200	Up To 4,200
GPD (Based on 120° Plenum Temperature)	Up To 12	Up To 17
Dimensions (Inches; HxWxD)	12.25 x 12 x 8.5	15 x 12 x 8.5
Weight (Pounds)	7	8
Replacement Vapor Pad® (Replace Once Per Season)	GA10 (GFI #7905)	GA35 (GFI #7902)
Installation	Warm Air / Return Air Plenum / Right or Left Side	
Plenum Opening (Inches)	9.125 x 9.125	9.125 W x 12 H
Bypass Opening (Inches)	6	
Pallet Quantity	36	30
Cabinet Construction	UV-Stable Automotive Grade Plastic	
Voltage (Volts)	24	
Warranty (Years)	5	
In The Box	Humidifier, Humidistat, Control Bypass Damper, 24V Transformer, Solenoid Valve, Vapor Pad®, Push-to-Connect Valve, Installation Manual, Mounting Template, Parts Kit.	



Learn More



Contractor Contact Information

Learn More at: www.GeneralFilters.com



General Filters 43800 Grand River Avenue Novi, Michigan 48375 Toll Free: (866) 476-5101 www.generalaire.com

All information subject to change without notice. Our Brands General Aire







